

| | 1197319 Index No: <u>X-13</u> |
|--|--|
| Statement of Bvi | |
| East Quarter Corner Sectio | |
| September 1878Original survey of 57-15 subdivision was run north on true line betweetpost was set 2' in the ground for the quarter corner to Sections 33 &6" SpruceN 15°E28 links (18.5')5" SpruceN 49°W06 links (4.0') | veen Sections 33 & 34, and at 40.00 chains (2640.0') a 4' 34 from which: |
| | Henry S. Howe U.S. Deputy Surveyor |
| <u>February 7th, 1918</u> Consolidated and. Re-named by Resolution of County Board as t which part is described as beginning at about the southeast corne Lines to the Southeast corner of Section 33, Twp.57, R. 15. | hat part of the Aurora Road, established July 6 th , 1906, r of Section 4, Twp. 57, R. 15, thence South on Section |
| August 07, 1978 Corner Card states that an Aluminum Capped Pipe (ACP) was set for on a fenceline to the east. Set the following ties: 10" Jack Pine N 56°W 10" Jack Pine N 56°W 8" Jack Pine N 38°E 79.24' (tag) Control Post West | or the corner on the C/L of Co. Rd. #344 (north-south) and |
| undated Partial subdivisions for Sections 33 & 34 show distances | of 2638.03' north to the NE Cor. Sec. 33, and 2642.53' |
| south to the SE Cor. Sec. 33. | St. Louis Co. Surveyor's Office |
| <u>November 01, 1995</u> A Certificate of Survey location map of Section 33 shows an ACP | for the corner with distances of 2638.21' north to the NE |
| Cor. Sec. 33, and 2642.40' south to the SE Cor. Sec. 33. | Northern Lights Surveying & Mapping |
| | LS #16089 |
| <u>June 26, 1996</u> A Certificate of Survey location map of Section 33 shows an ACP for the 1995 survey. | or the corner with the same distances north and south as |
| | Northern Lights Surveying & Mapping LS #16089 |
| <u>September 16, 2003</u> A Certificate of Survey in Section 33 shows an ACP for the corner w | ith a distance of 2642.27' south to the SE Cor. Sec. 33. Northern Lights Surveying & Mapping LS #16089 |
| June 30, 2011 Searched for and found the ACP for the corner 6" below the road g the ACP to search for any other monuments, but found none. Re occupied it with GPS-RTK (VRS method, Pt. #14, T57N-R15W.job) for p ties from 1978 and found: 12" Jack Pine N 38°E 79.24' (now dead, had nail 8 The other Jack Pine tie and Control Post were gone. Accepted the A and no other evidence was found to dispute it. Added the following for a first state of the ACP. The Search Pine Pine Pine Pine Pine Pine Pine Pine | eplaced the ACP where it was from the ties and directly brecise Latitude & Longitude (see front). Searched for the k tag) ACP for the corner as it is in harmony with local land lines new ties: |
| | Bruce Anderson, Greg Jacobson St. Louis Co. Public Works Dept./ Land Survey Division Tom O'Malley, County Surveyor |
| Return h PUbl Afr #: CashV/ | 200742 200742 (C CH3 |